From: Moore, Gary
To: Delgado, Eric
Subject: CES: Viper

Date: Wednesday, February 18, 2015 8:28:23 PM

Eric:

Daniel indicated that the viper system is not working properly so there is either a problem with the system or to much metal on the site. He indicated that he talked with you about it and you said to keep tinkering with it but I have him doing to much for it not to work consistently. Any suggestions?

Thanks

Gary Moore Federal On-Scene Coordinator U.S. EPA Region 6 214-789-1627 cell 214-665-6609 office

moore.gary@epa.gov